## Survey No. F-1-141

## Maryland Historical Trust State Historic Sites Inventory Form

Magi No. 1111415604
DOE \_\_yes X\_no

1. Nam	e (indicate pro	eferred name)				
historic						
and/or common	House on Bo	wersox Property				
2. Loca	ation					
street & number	West side Pleasant	View Road, between	Pleasant View Doubs and	not for publication		
city, town	Doubs	$\underline{X}$ vicinity of	congressional district			
state	Maryland	county	Frederick			
3. Clas	sification					
Category district X building(s) structure site object	Ownership public private both Public Acquisition in process being considered not applicable	Status X occupied unoccupied work in progress Accessible yes: restricted X yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:		
4. Own	er of Prope	<b>'ty</b> (give names ar	d mailing addresses	s of <u>all</u> owners)		
name						
street & number			telephone no	.:		
city, town state			and zip code			
5. Loca	ation of Lega	al Descriptio	n			
courthouse, regis	stry of deeds, etc.			liber		
street & number				folio		
city, town			state			
6. Repr	esentation	in Existing	Historical Surve	eys		
title						
date			federal state	county local		
pository for su	rvey records					
city, town			state			

## 7. Description

Survey No.F-1-141

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

This house is located close to the west side of Pleasant View Road, between Doubs and Pleasant View in southern Frederick County. The house faces east toward the road, and is  $2\frac{1}{2}$  stories high, gable roofed with a metal standing seam roof, and six bays wide by two deep. It is now sheathed with white asbestos shingle, and according to the owner, is of brick construction. There are two brick chimneys, one located inside the north gable end, and the other located between the second and third bays from the south.

The location of these chimneys, and the locations of door and window openings on the principal facade, suggest that the house may possibly have been built in two sections or built to serve two different functions. The two entrances on this facade, one in the second bay from the south end and one in the second bay from the north end, also suggest that the building may have been divided in two sections. The four north bays form a distinctly separate section, with window and door openings here generally evenly spaced. The south two bays, however, are set apart from the northern four bays by a much wider space; this section is also clearly demarcated by the location of the chimney between the second and third bays from the south. Windows are 6/6 double-hung sash. A one-story wooden porch extends across the length of the facade. A one-story ell is located to the rear of the house on the north end. The house is currently being renovated by its owners.

1400- 1500-	-1599 agriculture -1699 _X_ architecture -1799 art -1899 commerce	c c c c e e e e e e ii	communiticonservate economice education engineerii exploratio	y planning ion s	law literatu military music t philoso	ire y ophy s/government	religion cum science cum sculpture cum social/ humanitarial cum theater cum other (specif	on
Specific	dates	Build	ler/Archi	tect				
check:	Applicable Criteria:A and/or	В	C	D				
	Applicable Exception:	A	ВС	D	EF _	_G		
	Level of Significance: _	_natio	onal _	_state _	local			
Prepare	both a summary paragraph	of si	gnifica	ance and	a general	statement o	of history and	— d

Survey No. F-1-141

**Significance** 

support.

This house is significant architecturally as a type of vernacular building which is unusual in this area. The unusually long principal facade; the division of the facade into four-bay and two-bay sections, each with separate entrance; and the locations of the two chimneys, all suggest either that the building was constructed in two sections or that it was originally built for some other use than as a single family dwelling. The building also appears to be the earliest in date of the buildings which line the west side of Pleasant View Road to the north.

The building is shown on the 1873 Lake atlas of Frederick County, possibly as the E.F. Bowersox property or more likely as "B.& W.S.", which may refer to a blacksmith and wheelwright shop. An E.F. Bowersox is listed as a wheelwright under Adamstown in the 1880 Maryland Directory. See also survey site F-1-142 for information on the house directly north of this one, which was probably the Bowersox house.

## 9. Major Bibliographical References

Survey No. F-1-141

Lake, D.J., Atlas of Frederick County, Maryland, 1873.

The Maryland Directory, J. Frank Lewis and Co., Baltimore, 1880.

10. Ge	ograp	hical Data				
Acreage of nomi Quadrangle nam UTM References	ie	complete UTM refere	nces	Quadrangle	e scale	
A Zone Eastin	ng	Northing	B Zone	Easting	Northing	
C			D F H			
Verbal bounda	ry descript	ion and justification				
List all states	and countie	es for properties overla	pping state or	county boundaries		
state		code	county		code	
state		code	county		code	
11. For	m Pre	epared By				
name/title	Peggy Br	uns Weissman, Archi	tectural Hi	storian		
organization	Maryland	Historical Trust		date May 1982		
street & number	21 State	Circle		telephone (301) 26	9-2438	
city or town	Annapoli	S		state Maryland	21401	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.


return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438





F-1-141 House on Bowersox Property East Elevation Peggy Bruns Weissman June 1982